EDUCATIONAL SPACE & PROGRAM IMPROVEMENTS – CLINTON ELEMENTARY



- Upgrade interior door hardware
- Replace stair treads & landings

FACILITIES INFRASTRUCTURE:

- New roof/restoration
- Masonry restoration
- New exterior doors

BUILDING UTILITIES:

- Upgrade cabling, clock systems and P.A.
- New exterior LED light fixtures
- Upgrade air handling & ventilation
- New drinking fountains
- Kitchen drainage issues

EDUCATIONAL SPACE & PROGRAM IMPROVEMENTS:

Replace folding partition with roll-down curtain

SITE IMPROVEMENTS:

- Replace damaged sidewalks & curb
- Replace pavement
- Address flooding at sidewalk



CLINTON ELEMENTARY

Remove Folding Partition



New Exterior Doors

ST SENEC

Address Flooding At Sidewalk

New Roof/ Restoration